19-21 S. Washington Street (Commercial Building) (Tiffin Woolen Mill, Gordon Lumber Company) Tiffin Seneca County Ohio

HABS OHIO, TH-TIF,

HABS No. OH-2328

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS. OH!O, TH-TIF, 2-

March 18, 1988

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINI	rv
Ohio	Seneca			
			City of Tiffin	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR 19-21 S. Washington Street (Commer				HABS NO.
IS at 5. Washington bei	CCC (COMMCI			OH-2328
SECONDARY OR COMMON NAMES OF S Tiffin Woolen Mill, Gordon Lumber Company	STRUCTURE			
COMPLETE ADDRESS (DESCRIBE LOCA	TION FOR RURAL	SITES)		
19-21 S. Washington Str	reet			
DATE OF CONSTRUCTION (INCLUDE SO	OURCE)	ARCHITECT(S) (INCL	.UDE SOURCE)	
Circa 1900 (Ohio Historic Trust)		unknown		
SIGNIFICANCE (ARCHITECTURAL AND	HISTORICAL, INC	LUDE ORIGINAL USE (OF STRUCTURE)	
The building was built as the Ohio Historic Trust I century brick manufacturi	inventory.	It exemplifies	late 19th-	lls, according to early 20th
STYLE (IF APPROPRIATE) Brick Ma	nufacturing	/Commercial		
MATERIAL OF CONSTRUCTION (INCLU	DE STRUCTURAL .	SYSTEMS)		
Brick bearing flat tin r	coof, Wall tr	eatment-stretc	her bond	
HAPE AND OIMENSIONS OF STRUCTU	RE (SKETCHED FL	OOR PLANS ON SEPAR	ATE PAGES ARE A	ACCEPTABLE)
Building is rectangular, 183 foot depth (see sket EXTERIOR FEATURES OF NOTE The main feature is the rectangular windows over	ch attached Oriel windown each one o	w on the 2nd f f the oriel wi	loor topped	by two smaller oriel windows
are connected by a balco INTERIOR FEATURES OF NOTE (DESC!			pped by a co	(Over)
Floor plan sketch is att bare wood framing. Some of the building remain: MAJOR ALTERATIONS AND ADDITION 1915- Was used as the Ho 1919- Cole's Cleaning an	ached. The remnants however the SWITH DATES	interior has of partitions y are in poor 1924- New H	placed for o	commercial use
1921- Dermody and Mercha			hart's Upho	
PRESENT CONDITION AND USE				
Building is in dilapidat roof water damage, and r				
OTHER INFORMATION AS APPROPRIA	re Titles	-a.lun. Bull	uing is vac e	
Ohio; Historic Inventory "These two buildings, no as the twin across S. Wa	w used as or	ne, are twins		
SOURCES OF INFORMATION (INCLUDIA Seneca County Museum	NG LISTING ON NA	TIONAL REGISTER, ST	TATE REGISTERS,	ETC.)
Ohio Historic Trust Inve	entory			
Tiffin Historic Trust				
COMPILER, AFFILIATION			DAT	E

Paula A. Young, Tiffin Chamber of Commerce

19-21 S. Washington Street (Commercial Bldg) (Tiffin Woolen Mill, Gordon Lumber Company HABS No. OH-2328 (page 2)


(Exterior features, continued)

topped by a cornice with dentils and with several rows of bricks above the cornice. There is a small rectangular window in the center bay of the second floor. The backs of both sides have additions of later dates (unknown), which form a U-shaped plan because the center bay has not been extended. Part of one of these additions on the south was later demolished (dates unknown).


(Alterations and Additions, continued)

1961 - Pizza Villa 1970-1974 Vacant 1974-1977 - Faith Action 1977 - present - vacant

19-21 S. Washington Street (Commercial Building) (Tiffin Woolen Mill Bldg. Gordon Lumber Company) HABS No. OH- 2328 (page 3)



19-21 S. Washington Street (Commercial Bldg.) (Tiffin Woolen Mill, Gordon Lumber Company) HABS No. OH-2328 (page 4)



19-21 S. Washington Street (Commercial Bldg.) (Tiffin Woolen Mill, Gordon Lumber Company) HABS No. OH-2328 (page 5)

